



HOME OWNED & OPERATED

P.O. BOX 506 • BAXLEY, GEORGIA 31515

2174 HATCH PARKWAY SOUTH • BAXLEY, GEORGIA 31513 • Tel. (912) 367-1151

INVOICE
No. 10885



NAME	<u>Jim Lawrence</u>	ACCOUNT NO.	
MAIL ADDRESS	<u>205 O'Berry Dr.</u>	DATE ORDERED	
CITY/STATE/ZIP	<u>Baxley GA 31513</u>	DATE PROMISED	
PHONE	<u>912-278-0068</u>	DATE COMPLETED	<u>6-16-25</u>
LOCATION		TERMS	

INSTRUCTIONS install tankless water heater

QTY.	TAG NO. AND DESCRIPTION OF APPLIANCE/MATERIAL	UNIT PRICE	SALES AMOUNT
1	Rinnai V53De tankless water heater w/ isolation valves, serial # RK.CA-019435		1000 00
118'	1/2" coated copper tubing	3 29	388 22
1	Rago LV4403BY second stage regulator		69 95
1	1/2" cut off valve		16 95
6	1/2" flare nut	1 60	9 60
1	5/8" x 1/2" flare tee		6 99
2	1/2" swivel	3 99	7 98
2	1/2" x 1/2" male adaptor	3 09	6 18
all	other gas fittings, water fittings, bolt & nut for unistrut		29 20
TOTAL MATERIAL			1535 07

SERVICEMAN TO COMPLETE IN PRESENCE OF CUSTOMER:

1) STORAGE SYSTEM INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 59 ☐

2) ALL APPLIANCES INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 54 ☐

SERVICES PERFORMED

installed tankless water heater, repaired leak in ground by tank, ran pressure check

TOTAL TIME

HOURS

LABOR

260 00

SUBTOTAL

SALES TAX

122 81

TOTAL DUE

1,917 88

- GSA rebate - 200 00

AMOUNT RECEIVED \$ 1,717.88

RECEIVED BY

DATE

SERVICES RECEIVED BY

THE ODOR CHARACTERISTICS HAVE BEEN DEMONSTRATED TO ME.

SERVICES PERFORMED

BY

[Signature]

CUSTOMER'S SIGNATURE

SERVICEMAN MUST COMPLETE BELOW SECTION FOR NEW INSTALLATIONS OR SERVICE

INSTALLATION OR TURN ON	REMOVAL OR TURN OFF	LEAK AND PRESSURE TEST	
		HIGH	LOW
SIZE:	SIZE	START LOCK UP:	START LOCK UP:
S/N:	S/N:	TANK OFF PRESSURE:	TANK OFF PRESSURE:
GALLONS OR READING:	GALLONS OR READING:	AFTER 10 MINUTES:	AFTER 10 MINUTES:
		PRESSURE AS LEFT:	PRESSURE AS LEFT:

WHITE/CUSTOMER'S COPY; YELLOW/POSTING COPY; PINK/FILE COPY

GASCheck - Gas Appliance System Check

Account Name _____ Invoice Number _____ Date 6/16/25
 Name Jim Lawrence Company Sikes Propane, Inc.
 Address 205 O'Berry Dr. Call Taken By _____
 City Baxley State GA Zip 31513 Telephone (Cell) 912-278-0068 (Home) _____
 Appliance Check

Appliance	water heater	water heater	gas logs	griddle	grill	smoker
Manufacturer	<u>Rinnai</u>	<u>Rinnai</u>	<u>Peterson</u>	<u>Black Stone</u>	<u>Ran Kam</u>	<u>Smoke Hollow</u>
Model #	<u>V53De</u>	<u>RL75e</u>	<u>G10-24/30-15CM)P</u>	<u>1554</u>	<u>GR2039201-MM-00</u>	<u>PS4415</u>
Serial #	<u>RK.CA-019435</u>	<u>JE.CA-058202</u>	<u>1291532</u>	<u>1410155901713</u>	<u>06215030007445</u>	<u>KB201511965</u>
BTU's	<u>120,000</u>	<u>180,000</u>	<u>37,000</u>	<u>60,000</u>	<u>116,000</u>	<u>22,000</u>
Burner - Cons. Chamber	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>
Man. Shutoff - Sed. Trap	<u>installed</u>	<u>existing</u>	<u>existing</u>	<u>existing</u>	<u>existing</u>	<u>existing</u>
Control - Pilot Safety System	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>
Venting System	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>
Age	<u>new</u>	<u>8yrs.</u>	<u>8yrs.</u>	<u>10yrs.</u>	<u>10yrs.</u>	<u>10yrs.</u>
Taken Out Of Service Or Operation						

Container Check

Size	Serial #	Manufacturer	MFR. Date	Location	Container Condition	Relief Valve	Fittings Leak Check
<u>150</u>	<u>304061</u>	<u>Quality Steel</u>	<u>1990</u>	<u>ok</u>	<u>ok</u>	<u>6C15</u>	<u>ok</u>

Pressure Test (If Applicable)

Start Pressure	End Pressure	Time Held	Pressure Held	Work Order
<u>125psi.</u>	<u>125psi.</u>	<u>10min.</u>	<u>0</u>	<u>0</u>

System Leak Check

Start Pressure	End Pressure	Time Held	Pressure Held	Work Order
<u>9in.wc.</u>	<u>9in.wc.</u>	<u>10min.</u>	<u>0</u>	<u>0</u>

Regulator Check

Type	Manufacturer	Date / Model	Vent Position/Protection
<u>first</u>	<u>Rego</u>	<u>02C15 / LV4403TR9</u>	<u>u-c</u>
<u>second</u>	<u>Rego</u>	<u>12-2018 / LV4403B4</u>	<u>down</u>
<u>second</u>	<u>Rego</u>	<u>01C17 / LV3403B4</u>	<u>down</u>
<u>second</u>	<u>Rego</u>	<u>07C15 / LV3403B4</u>	<u>down</u>

Safety Information Supplied:

Comments: Please note all repairs and corrections made along with any recommended actions