

the Lugo Construction



HOME OWNED & OPERATED

P.O. BOX 506 • BAXLEY, GEORGIA 31515
2174 HATCH PARKWAY SOUTH • BAXLEY, GEORGIA 31513 • Tel. (912) 367-1151

INVOICE
No. 10770

NAME	<u>Ken Heaton</u>	ACCOUNT NO.	
MAIL ADDRESS	<u>Po. Box 396</u>	DATE ORDERED	
CITY/STATE/ZIP	<u>Alma GA 31510</u>	DATE PROMISED	
PHONE	<u>1-703-232-6314</u>	DATE COMPLETED	<u>6-18-24</u>
LOCATION		TERMS	

INSTRUCTIONS rough-in for new house

QTY.	TAG NO. AND DESCRIPTION OF APPLIANCE/MATERIAL	UNIT PRICE	SALES AMOUNT
1	Rinnai RE199e tankless water heater w/isolation valves, serial # RC.UA-047785		1500 00
1	Rinnai RE180 tankless water heater w/isolation valves, serial # RE.UA-062575		1285 00
2	RGBRE recess box	319 00	638 00
1	500 gallon AG/UG, 2023 Quality Steel tank		3800 00
1	Anode bag for tank		200 00
1	Empira 36" Rushmore, Less, blower, liner		5900 00
All	Dura Vent 5"x8"		1500 00
All	1" poly pipe, transition fitting, tee, elbows		1192 44
TOTAL MATERIAL			16,015 44

SERVICEMAN TO COMPLETE IN PRESENCE OF CUSTOMER:

- 1) STORAGE SYSTEM INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 58 ☐
- 2) ALL APPLIANCES INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 54 ☐

THE ODOR CHARACTERISTICS HAVE BEEN DEMONSTRATED TO ME.

X
CUSTOMER'S SIGNATURE

SERVICES PERFORMED

ran all gas lines

inside house, & poly pipe outside, trenching around house, installed two tankless water heaters with recess boxes, installed Rushmore, installed 500 gallon AG/UG tank & Lockett

SERVICES PERFORMED

BY

[Signature]

TOTAL TIME _____ HOURS

LABOR 3110 00

SUBTOTAL

SALES TAX 1281 24

TOTAL DUE 20,406 68

SERVICEMAN MUST COMPLETE BELOW SECTION FOR NEW INSTALLATIONS OR SERVICE

INSTALLATION OR TURN ON	REMOVAL OR TURN OFF	LEAK AND PRESSURE TEST	
		HIGH	LOW
SIZE: <u>500</u>	SIZE	START LOCK UP:	START LOCK UP:
S/N: <u>1492199</u>	S/N:	TANK OFF PRESSURE:	TANK OFF PRESSURE:
GALLONS OR READING: <u>400 gal</u>	GALLONS OR READING:	AFTER 10 MINUTES	AFTER 10 MINUTES:
		PRESSURE AS LEFT:	PRESSURE AS LEFT:

AMOUNT RECEIVED \$ _____

RECEIVED BY _____

DATE _____

SERVICES RECEIVED BY _____

WHITE/CUSTOMER'S COPY; YELLOW/POSTING COPY; PINK/FILE COPY

800.00
relate requested callin
5-1-25
H

GASCheck - Gas Appliance System Check

Account Name _____ Invoice Number _____ Date 4 / 22 / 25
 Name Ken Heaton Company Sikes Propane, Inc.
 Address Po. Box 396 Call Taken By _____
 City Alma State GA Zip 31510 Telephone (Cell) 703-232-6314 (Home) _____

Appliance Check

Appliance	water heater	water heater	gas	gas	cooktop	gas	other
Manufacturer	Rinnai	Rinnai	Peterson	Empire	Thor	MHP	55207
Model #	RE199e	RE180	G10-24/30-15(M)P	DVCT36CB P95P-3	HRT3618K	WK-005	56756
Serial #	RC.4A-04 7785	RE.4A-06 2575	2057294	231819877	HRT3618K22 12068	56755	56761
BTU's	199,000	180,000	37,000	40,000	87,000	1960	56757
Burner / Com. Chamber	ok	ok	ok	ok	ok	ok	56759
Man. Shutoff / Sed. Trap	installed	installed	installed	installed	installed	installed	56762
Control / Pilot Safety System	ok	ok	ok	ok	ok	ok	56758
Venting System	ok	ok	ok	ok	ok	ok	56763
Combustion Air	new	new	new	new	new	new	56754
Taken Out Of Service Or Operation			30"	36"		(X11)	56760

Container Check

Size	Serial #	Manufacturer	MFR. Date	Location	Container Condition	Relief Valve	Fittings Leak Check
500	1492199	Quality Steel	2023	ok	ok	12D22	ok

Pressure Test (If Applicable)

Start Pressure	End Pressure	Time Held	Pressure Held
110 psi.	110 psi.	10 min.	Work Order

System Leak Check

Start Pressure	End Pressure	Time Held	Pressure Held
9 in. wc.	9 in. wc.	10 min.	Work Order

Piping Check

Materials	Size	Cover / Protection
poly pipe	1"	ok
coated copper	1/2" + 3/8"	ok

Regulator Check

Type	Manufacturer	Date / Model	Vent Position / Protection
first	Rego	06D2024 / LV4403TR9	h-c
second	Rego	06E2022 / LV4403B66R	down
second	Rego	09C2021 / LV4403B66	down
second	Rego	04C2024 / LV4403B66R	down
second	Rego	10D2023 / LV3403B4	down
second	Rego	10D2023 / LV3403B4	down

(X3)

Comments: Please note all repairs and corrections made along with any recommended actions.