### INVOICE



Sikes Propane

2174 Hatch Parkway South Baxley GA 31513 9123671151

Date: 09/30/2025

Time: 08:07 am

CHRISTY REESE

Time In: 8:07 AM

Time Out:

SOUTHERN GRAPHICS NEW BUILDING

Acc# 250926135750

Sub Account# 250926135750

1472 Golden isle west Baxley, ga 31513

mail:

Phone Number:

Order #:

Invoice #: 250930080750

Tank Serial #: 2SA054562

Summary (*Itemized list at the back)	Total	
		\$12075.00
Parts & Fittings		\$0.00
Labor	Subtotal Discount Taxes Grand Total (\$)	\$12075.00 \$1000.00 \$966.00 12041.0

<sup>\*</sup> All applicable sales tax will be added at time of final billing unless otherwise specified here.

### Job Description:

We are excited about the possibility of working with you,

By signing this document, the customer agrees to the services and conditions outlined in this document.

Customer Signature:

Signed On: 09-30-2025 08:15 am

Part #	Category	Description	Price(\$)	Quantity	Hours	Hourly Rate	Total(\$)
RE140eP	Parts & Fittings	RE140eP-Rinnai 140eP (Propane)	1075.0	1	N/A	N/A	\$1075.00
Trane Central Heater	Parts & Fittings	Trane S9X1C100U5PSBBA	5500.0	2	N/A	N/A	\$11000.00
					Subtotal		\$12075.00
					Discount		\$1000.00
					Taxes		\$966.00
				Gran	d Total(\$)		\$12041.00



# Sikes Propane Safety Check

Customer name: SOUTHERN GRAPHICS NEW BUILDING	VG Date: 09-16-2025	
Street: 1472 Golden isle west		
State: ga	Zip: 31513	
Account No: 250926135750	Sub Acc. Number 250926135750	5750
Customer Email	Phone Number:	
Purpose Of Service:	Salesman Name: Daniel Sikes	3.6
Public Assembly	∇ New Appliance Service	Leak Check
☐ New Customer Installation Service	☐ Out Of Gas	System Repair Service
Codor Complaint	☐ Move-in(New Renter/Owner)	Cother Services
☐ Line Locate	Cutside Visual Inspection	
Disclaimer: This inspection covers gas equipment an of inspection. It does not cover latent or manufacturir or unforeseen happenings.	Disclaimer: This inspection covers gas equipment and appliances visible and readily accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal workings of sealed equipment or structural components and cannot be construed to cover future or unforeseen happenings.	
Tank/Cylinder:		technician and represents the conditions existing on the date structural components and cannot be construed to cover future
Size:	Tank 1	cian and represents the conditions existing on the date iral components and cannot be construed to cover future
Serial No:	Tank 1 120	cian and represents the conditions existing on the date iral components and cannot be construed to cover future
	Tank 1 120 2SA054562	cian and represents the conditions existing on the date ral components and cannot be construed to cover future

Cap On Relief Valve:

Yes

### High Pressure Test:

	Initial	Retest
Start Pressure:	110 P.S.I	
End Pressure:	110 P.S.I	P,S,I
Start Time:	04:30:PM	
End Time:	04:40:PM	
Time Held:	10	
Pressure Held:	¥₽₽	Voa

## Intermediate Pressure Test:

Pressure Held:	Time Held:	End Time:	Start Time:	End Pressure:	Start Pressure:	
Yes				P.S.I	P.S.I	Initial
Yes				P.S.I	P.S.I	Retest

### Appliances:

Transition of the state of the	Water Heater	Central Heating System	Central Heating System
lds:			
Manufacturer:	Rinnal	Trane	
Year Manufactured:	2023	2024	
Model:	RE140e	S9X1C100U5PSBBA	S9X1C100U5PSBBA
Btu:	140000	100000	100000
Serial No:	SG.UA-104944	25031RBTKG	25031P3AKG
Manual Shutoff:	Existing	Existing	Existing
Sediment Trap:	NA	NA	
Vented:	NA	NA	
Warning Tag:	NA	NA	
Warning Tag Number:			
Warning Tag Comments:			

Disclaimer: This inspection covers gas equipment and appliances visible and readily accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal workings of sealed equipment or structural components and cannot be construed to cover future or unforeseen happenings.

images

09-26-2025	09-26-2025
Customer Signature	Employee Signature
SOUTHERN GRAPHICS NEW BUILDING	DANIEL SIKES
▼ I SOUTHERN GRAPHICS NEW BUILDING have read and fully understand this certification.	$oldsymbol{arphi}$ I certify that I have completed the system check and installation review as described above.
	Locked tank out with POL lock?.
Disclaimer: This inspection covers gas equipment and appliances visible and readily accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal workings of sealed equipment or structural components and cannot be construed to cover future or unforeseen happenings.	Disclaimer: This inspection covers gas equipment and appliances visible and readily accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal workings of sealed equipment or structural components and cannot be construed to cover future or unforeseen happenings.
	I am satisfied with the service work performed.
members.	${f Z}$ I have received safety information and been told to read it and share it with all family members.
n monoxide detectors per manufacturer's instructions listed by Underwriters Laboratories.	₹ I have been told to consider installing one or more propane gas detectors and carbon monoxide detectors per
I have been told that the odorant giving propane its distinctive smell can fade or diminish in intensity and that certain physical limitations or conditions might prevent me from melling a gas leak.	I have been told that the odorant giving propane its distinctive smell can fade or dimimelling a gas leak.
have been shown how to turn the gas off at the container.	🗸 I have been told what to do if I smell a gas odor or otherwise suspect a gas leak and have been shown how to
	I have smelled the propane gas and can detect its odor.
ny property.	$oldsymbol{ec{ec{ec{ec{ec{ec{ec{ec{ec{ec$
ng installation of new appliance, so a leak check and system test can be completed.	I will notify propane company if propane service is interrupted for any reason, including installation of new appliance, so a leak check and system test can be completed.