

Billed to
Eddie Lago
Construction



INVOICE

11095

HOME OWNED & OPERATED

P.O. BOX 506 • BAXLEY, GEORGIA 31515
2174 HATCH PARKWAY SOUTH • BAXLEY, GEORGIA 31513 • Tel. (912) 367-1151

NAME	Daniel Bradley	ACCOUNT NO.	
MAIL ADDRESS	11 Shellworth Xing	DATE ORDERED	
CITY/STATE/ZIP	Savannah GA 31411	C. TE PROMISED	11-23-24
PHONE	404-805-5000	DATE COMPLETED	12-14-24
LOCATION		TERMS	

INSTRUCTIONS install three tankless water heaters + recess boxes

QTY.	TAG NO. AND DESCRIPTION OF APPLIANCE/MATERIAL	UNIT PRICE	SALES AMOUNT
3	Rinnai V53De tankless water heaters w/insulation valves + T-rd	1050 00	3150 00
3	Rinnai R6BRE recess box	319 00	957 00
3	Rinnai LV3403B4 second stage regulator	59 95	179 85
3	1/2" cut off valve	12 95	38 85
3	1/2" swivel	3 99	11 97
3	1/2" x 3/4" female adapter	3 19	9 57
8'	1/2" trap pipe counterstrike pipe	5 09	40 72
6	1/2" trap pipe auto flare	22 99	137 94
6	3/4" pex male adapter	2 89	17 34

SERVICEMAN TO COMPLETE IN PRESENCE OF CUSTOMER: 1) STORAGE SYSTEM INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 58 ☐ 2) ALL APPLIANCES INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 54 ☐	SERVICES PERFORMED	TOTAL MATERIAL	
	installed three tankless water heaters with recess boxes went back + moved two recess boxes + water heaters	4,543 24	
	TOTAL TIME	HOURS	LABOR
			800 00
THE ODOR CHARACTERISTICS HAVE BEEN DEMONSTRATED TO ME.	SERVICES PERFORMED	SUBTOTAL	
	BY <i>[Signature]</i> C.J. Ben	SALES TAX 363 46	
X CUSTOMER'S SIGNATURE		TOTAL DUE 5,706 70	

SERVICEMAN MUST COMPLETE BELOW SECTION FOR NEW INSTALLATIONS OR SERVICE

INSTALLATION OR TURN ON	REMOVAL OR TURN OFF	LEAK AND PRESSURE TEST		AMOUNT RECEIVED \$
		HIGH	LOW	
SIZE:	SIZE	START LOCK UP:	START LOCK UP:	RECEIVED BY
S/N:	S/N:	TANK OFF PRESSURE:	TANK OFF PRESSURE:	DATE
GALLONS OR READING:	GALLONS OR READING:	AFTER 10 MINUTES:	AFTER 10 MINUTES:	SERVICES RECEIVED BY
		PRESSURE AS LEFT:	PRESSURE AS LEFT:	

WHITE/CUSTOMER'S COPY; YELLOW/POSTING COPY; PINK/FILE COPY

GASCheck - Gas Appliance System Check

Account Name _____ Invoice Number _____ Date 12/14/24
 Name Daniel Bradley Company Sikes Propane, Inc.
 Address 1754 Gus Davis Rd. Call Taken By _____
 City Lyons State GA Zip 30436 Telephone (Cell) 404-805-5000 (Home) _____

Appliance Check

Appliance	<u>water heater</u>	<u>water heater</u>	<u>water heater</u>	<u>Generator</u>		
Manufacturer	<u>Rinnai</u>	<u>Rinnai</u>	<u>Rinnai</u>	<u>Generac</u>		
Model #	<u>V53De</u>	<u>V53De</u>	<u>V53De</u>	<u>G0072101</u>		
Serial #	<u>RH.CA-0170</u>	<u>RG.CA-0144</u>	<u>RH.CA-0170</u>	<u>3013254765</u>		
	<u>26</u>	<u>30</u>	<u>01</u>			
BTU's	<u>120,000</u>	<u>120,000</u>	<u>120,000</u>	<u>355,000</u>		
Burner / Com. Chamber	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>		
Man. Shutoff / Sed. Trap	<u>installed</u>	<u>installed</u>	<u>installed</u>	<u>installed</u>		
Control / Pilot Safety System	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>		
Venting System	<u>ok</u>	<u>ok</u>	<u>ok</u>	<u>ok</u>		
Age	<u>new</u>	<u>new</u>	<u>new</u>	<u>new</u>		
Taken Out Of Service Or Operation						

Container Check

Size	Serial #	Manufacturer	MFR. Date	Location	Container Condition	Relief Valve	Fittings Leak Check
<u>500</u>	<u>1523666</u>	<u>Quality Steel</u>	<u>2024</u>	<u>ok</u>	<u>new</u>	<u>09D22</u>	<u>ok</u>

Pressure Test (If Applicable)

Start Pressure	End Pressure	Time Held	Pressure Held
<u>120psi.</u>	<u>120psi.</u>	<u>10min.</u>	<u>0</u>
			<u>Work Order</u>
			<u>0</u>
			<u>N</u>

Piping Check

Materials	Size	Cover / Protection
<u>poly pipe</u>	<u>1"</u>	<u>ok</u>
<u>coated copper</u>	<u>1/2" + 3/8"</u>	<u>ok</u>
<u>Trac pipe</u>	<u>1/2"</u>	<u>ok</u>

System Leak Check

Start Pressure	End Pressure	Time Held	Pressure Held
<u>9in.wc.</u>	<u>9in.wc.</u>	<u>10min.</u>	<u>0</u>
			<u>Work Order</u>
			<u>0</u>
			<u>N</u>

Regulator Check

Type	Manufacturer	Date / Model	Vent Position / Protection
<u>first</u>	<u>Rego</u>	<u>06D2024 / LV4403TR9</u>	<u>n-c</u>
<u>second</u>	<u>Rego</u>	<u>04C2024 / LV4403B66R</u>	<u>down</u>
<u>second</u>	<u>Rego</u>	<u>10D2023 / LV3403B4</u>	<u>down</u>

(X3)

Safety Information Supplied:

Comments: Please note all repairs and corrections made along with any recommended actions