



congerlpgas.com

Gas

127339

146 S. Ridge Ave. Tifton, GA 31794 (229) 386-5574

306 S. Main St. Sylvester, GA 31791 (229) 776-7336

604-B N. Broadfoot Blvd. Vidalia, GA 30474 (912) 537-8722

3117 Veterans Parkway S. Moultrie, GA 31788 (229) 985-6942

2310-B Highway 84 W Valdosta, GA 31602 (229) 469-4250

NAME Robinson Stinson RT# _____ RT. SEQ. _____ ACCT # 03-24199 DATE 3-17-26 INT 1

MAILING ADDRESS _____ CO. _____ CITY _____

ADDRESS 274 Whitfield rd APT/LOT NO. _____

CITY Moultrie STATE GA ZIP CODE 31768

NEW CUSTOMER INFORMATION

S.S. NO. _____ DELV _____
 HOME PH _____ RENT _____
 WORK PH _____ CREDIT _____
 LITE PILOT _____ PC _____
 EMPLOYER _____
 DR. _____ USE _____ LEASE _____

email: RobinsonStinson73@gmail.com
 cell # 989-454-9623

PAY BILL ONLINE @congerlpgas.com

SERVICE REQUESTED: CASH CHARGE DATE PROMISED _____

finish job

DIRECTIONS: 120g 2 W/H, Logs, Cooktop

TANK PICKUP/SET	TANK SIZE	SERIAL #	TANK %	TANK DESTINATION	DOT PERMANENTLY INSTALLED CONTAINERS				
					MANUFACTURED DATE	LAST TEST DATE	SIZE	SERIAL #	% FULL
<u>TS</u>	<u>123</u>	<u>U-236418</u>	<u>10gal</u>	<u>Algon Site</u>					
		<u>10 X 4.099 =</u>						<u>65</u>	<u>33</u>

QTY	APPLIANCES / EQUIP. SOLD-PARTS/MATERIAL USED	MODEL #	SERIAL NUMBER	UNIT PRICE	SALES AMOUNT
<u>1</u>	<u>RE 160e</u>	<u>WB UA-012010</u>			<u>1099 95</u>
<u>1</u>	<u>RE 160e</u>	<u>WB UA 012007</u>			<u>1099 95</u>
<u>40</u>	<u>1/2 Poly + Trencher Fee</u>				<u>176 00</u>
<u>15</u>	<u>1/2 Copper</u>				<u>119 25</u>
<u>2</u>	<u>Copperset & 2 Sediment Trap</u>				<u>299 80</u>
<u>1</u>	<u>1/4" R Regulator</u>				<u>104 95</u>
<u>3</u>	<u>Cutoff Valves</u>				<u>89 85</u>
<u>4</u>	<u>Flare Nuts</u>				<u>15 80</u>
<u>1</u>	<u>Flex Connector & 3 MIP</u>				<u>49 80</u>

WORK PERFORMED: Set tank, trench line to house - Made final connections

REGULATION INFORMATION

MAKE: Rego MODEL: TR9 DATE CODE: 10B2025 VENT: Down

APPLIANCES/EQUIP. SOLD WH 1099 95

PARTS/MAT. USED WH 1099 95

TANK RENT MP 855 45

SERVICEMAN MUST COMPLETE BELOW SECTION FOR NEW INSTALLATIONS OR SERVICE

SERVICEMAN TO COMPLETE IN PRESENCE OF CUSTOMER:

1) STORAGE SYSTEM INSTALLED IN COMPLIANCE WITH N.F.P.A. PAMPHLET NUMBER 58

2) ALL APPLIANCES INSTALLED IN COMPLIANCE WITH N.F.P.A PAMPHLET NUMBER 54

I HAVE RECEIVED A SCRATCH AND SNIFF BROCHURE AND THE ODOR CHARACTERISTICS HAVE BEEN DEMONSTRATED TO ME.

X _____ CUSTOMER SIGNATURE

LEAK AND PRESSURE TEST				SALES TAX
HIGH:	1st Stage	2nd Stage	LOW	%
START LOCK-UP:	<u>10</u> PSI	PSI	START LOCK-UP:	<u>99.00</u>
TANK OFF: PRESSURE	<u>6</u> PSI	PSI	TANK OFF: PRESSURE	<u>76.99</u>
AFTER 10 MINUTES:	<u>6</u> PSI	PSI	AFTER 10 MINUTES:	<u>7.69</u>
PRESSURE AS LEFT:	<u>10</u> PSI	PSI	PRESSURE AS LEFT:	<u>1.71</u>

LABOR LB 560 00

MIS MS 84 93

TP TP 10 00

GP GP 4000 07

INV. TOTAL 3679.80

AMOUNT RECEIVED GP 400.00

THE USE AND CARE OF THE APPLIANCES AND EQUIPMENT HAVE BEEN EXPLAINED TO MY SATISFACTION. I ALSO ACKNOWLEDGE RECEIPT OF THE CUSTOMER COPY EXPLAINING THE SAFETY FEATURES OF SUCH EQUIPMENT ON THE REVERSE SIDE.

[Signature]
SERVICE REPRESENTATIVE SIGNATURE

4.24.2026 X
DATE

4079.80
CUSTOMER SIGNATURE



Residential Gas Appliance System Check

Company/Location Conger Moultrie

Call Date _____

Date GAS Check® Requested _____

Call-Taker's Name _____

Instructions _____

Account Number 03.24122
 Name Robinson Stinson
 Address 274 Whitfield Rd
 City, State, Zip Moultrie GA 31768
 Telephone: Office Home

PERFORMANCE CHECK: ITEM	Central Heating 1	Room Heating 2	Water Heater 3	Range 4	Clothes Dryer 5	6
Manufacturer	Rinnai	Peterson	Rinnai	Wolf		
Model No.	RE160	610243001VP	RE160	SRT486G		
Serial No.	WB.UA.012007	2065 659	WB.UA.012010	18683697		
Fuel	LP	LP	LP	LP		
BTU Rating	160K	37K	160K	65K		
Manual Shut-off (Installed/Existing)	Installed	Installed	Installed	Exists		
Sediment Trap (Installed/Existing)	Installed	-	Installed	-		
Control Mfr./Model No.	OK	OK	OK	OK		
Pilot(s)/Pilot Safety System	OK	OK	OK	OK		
Ignition System(s): Mfr./Model No.	OK	OK	OK	OK		
Thermostats: Mfr./Model No.	OK	OK	OK	OK		
Burner(s)/Combustion Chamber	OK	OK	OK	OK		
Venting System/Draft Diverter	OK	OK	OK	OK		
Combustion Air	OK	OK	OK	OK		
Red Tag (removed from service)/Recall	-	-	-	-		

TANK/CYLINDER (Additional Serial Numbers):

SIZE	SERIAL NUMBER	MFR.	MFR. DATE	LAST TEST DATE	LOCATION	CONDITION OF:					RELIEF VALVE			FITTINGS LEAK TEST
						TANK	PAINT	PIGTAIL	FITTINGS	GAUGE	COND.	DATE	CAP	
123	U236418	Cytsa	2005	2025	AG on Site	OK	OK	OK	OK	OK	OK	25	OK	-

PIPING/REGULATOR OPERATION/CONDITION

SINGLE STAGE	PIPING		REGULATOR MFR. DATE (CODE)	MFR.	REGULATOR CONDITION	MODEL	REG. VENT POSITION	HOW PROTECTED	FLOW PRESSURE	LOCK-UP PRESSURE			
	MATERIAL	SIZE								IN WC	IN WC		
SECOND STAGE	1st	Copper & Poly	1/2	10B2025	Rego	OK	TR9	Down	Some	PSIG	10	PSIG	
	2nd	TRAC	1/2	04E2024	Rego	OK	446R	Down	-	IN WC		IN WC	
THIRD STAGE		TRAC	1/2	NR	MAXITROL	OK	325-3L	Horizontal		11.5	IN WC	13	IN WC

SYSTEM LEAK TEST

SINGLE STAGE/ INTEGRAL/ SECOND STATE	START PRESSURE (INCHES WC)	END PRESSURE (INCHES WC)	TIME HELD	SYSTEM OK	
SECOND STAGE	1st	6	6	10m	OK
	2nd				
THIRD STAGE					

Comments Set tank. Trenched gas line to house - Hung Water Heaters - Made final connections to appliances

Reference Invoice No. 127339 Date 4.24.2026

I, Taylor Newsome (please print name) certify that I have completed the System Check as prescribed.

- Performed Odor Test Yes
- Performed Leak/Pressure Test Yes
- Placed Safety Decal Yes
- Left Consumer Safety Information and Material Yes

This inspection covers (propane/LP-gas) items and equipment visible and accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal working of sealed equipment, or structural components, and cannot be construed to cover future or unforeseen happenings.

I, _____ (Please print name)

- Know how to turn off the gas in case of emergency.
- Have smelled propane and can detect its odor.
- Have received the consumer safety information and material.
- Had gas system deficiencies and/or corrections, if any, clearly explained to me.
- Am satisfied with the service work performed.